ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0031, W0018, W0022, W0020, W0081, W0062, W0026, W	NA, 14th Crs	OLD JUNJAPPA TEMPLE SURROUNDINGS
Segment No.	**Total Length (m)**	
13/C-W0031/S050521	321.69	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	34.01	77.512414	13.059245	77.512707	13.059134	I0231	DEAD END
2	112.50	77.512143	13.056946	77.512258	13.057957	W0029	DEAD END
3	68.48	77.512397	13.059360	77.512537	13.059963	W0031	DEAD END
4	71.67	77.512179	13.059627	77.512807	13.059426	W0026	I1009
5	35.03	77.512586	13.059845	77.512908	13.059855	W0060	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
CONSTRUCTION OF RCC DRAIN NEAR OLD JUNJAPPA TEMPLE SURROUNDINGS AREA AND OTHER ROADS	5000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	RCC DRAIN WORK	013-17-000012
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/65/2016-17	02/09/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9900333496		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		G NAGABHUSHAN

Date of Inspection	Remarks
26/10/2016	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDHEGOWDA	26/10/2016	25/11/2016	COMPLETED
EE	DODDAIAH	26/10/2016	25/11/2016	COMPLETED
AEE	JAYALINGAPPA	26/10/2016	25/11/2016	COMPLETED
AE	G NAGABHUSHAN	26/10/2016	25/11/2016	COMPLETED
AE	G NAGABHUSHAN	26/10/2016	25/11/2016	COMPLETED

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0031, W0018, W0022, W0020,

Field Inspection Details

Number of Trees	Any Other Information	Name
0		G NAGABHUSHAN

Date of Inspection	Remarks
26/10/2016	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDHEGOWDA	26/10/2016	25/11/2016	COMPLETED
EE	DODDAIAH	26/10/2016	25/11/2016	COMPLETED
AEE	JAYALINGAPPA	26/10/2016	25/11/2016	COMPLETED
AE	G NAGABHUSHAN	26/10/2016	25/11/2016	COMPLETED
AE	G NAGABHUSHAN	26/10/2016	25/11/2016	COMPLETED

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0031, W0018, W0022, W0020,